

25X1A2g
[REDACTED]

IN 12297

25X1A2e 1. [REDACTED]

2. FIVE APPROX ONE ZERO ZERO FOOT TEST STRIPS PROCESSED
AS FOLL WITH RESULTS INDICATED:

25X1A2e

A. NORMAL PROCESSING ESTABLISHED BY [REDACTED] INCLUDING
DOUBLE STRENGTH NOVEMBER HOTEL DASH FIVE HARDNER. RESULTS:
STICKINESS IN DRYER. *NH-5*

B. REPEAT OF TEST ALFA ABOVE, EXCEPT DEVELOPER AND
SHORTSTOP OMITTED. RESULTS SAME AS ALFA, ABOVE.

C. NORMAL PROCESSING, OMITTING DEVELOPER USING TRIPLE
STRENGTH HARDNER. RESULTS: SEVERE STICKINESS IN DRYER.

D. DEVELOPER AND SHORTSTOP OMITTED. USING QTE POWDERS,
FIXING BATH HARDNER UNOTE ADDED TO LIQUID HYPO. RESULTS SAME
AS ALFA AND BRAVO, ABOVE.

8c1000

E. AEROSOL, DEVELOPER AND SHORTSTOP OMITTED. NOVEMBER
HOTEL DASH FIVE USED ACCORDING TO MANUFACTURERS INSTRUCTIONS.
RESULTS SAME AS ALFA, BRAVO AND DELTA, ABOVE.

3. PPEARS THAT HARDNER NOT BASIS OF PROBLEM STICKINESS
IN DRYER. TEST LEADEN RUN THROUGH DRYER WET INDICATES NO
PROBLEM WITHIN DRYER. TESTING WILL BE CONTINUED. REQUEST

25X1A2e [REDACTED] COMMENTS ADVICE SOONEST.

25X1A2e

25X1A2g CFN: [REDACTED] [REDACTED] HARDNER HYPO AEROSOL NOT
NO

~~SECRET~~